

IN THE SPECIFICATION:

Please amend the paragraph beginning at page 5, line 26 and ending at page 6, line 11, as follows.

--When the sheet to which the developer was transferred is sent to a fixing unit 313, developer fixing processing is performed. After the sheet is passed through the fixing unit 313, the sheet is temporarily directed from a path ~~351~~ 315 to a path 314 by a flapper (not shown), and, after a trailing end of the sheet leaves the path 315, the sheet is switched back to direct the sheet from a path 316 to a pair of discharge rollers 317. In this way, the sheet can be discharged out of the print unit 300 by the pair of discharge rollers 317 with the imaged surface (to which the developer was transferred) facing downwardly (face-down). This is referred to as reversal discharging.--